

To Our Customers

Survey report about SVHC 174

We report that our products do not contain any of SVHC 174 (0.1 %wt or more) except the following series as shown in Table-1.

For the other products such as customized capacitors and function modules, please contact us separately.

Our products: Standard capacitors listed in catalogue No. CAT.8100F (English version)/CAT.1000E (Japanese version)

SVHC 174: 174 substances published by July 7, 2017 from ECHA (European Chemical Agency) as substances of very high concern (SVHC) in accordance with Article 59 (10) of the REACH Regulation.

Table-1: SVHC 174 contained product list

| Type of capacitors | Series | SVHC | CAS No. (Decision No.) | Material name that contains SVHC |
|--------------------|--------|-------------------------------------------------------------|--------------------------|----------------------------------|
| Type 1 * | LNR | Bis(2-ethylhexyl) phthalate [DEHP] (※1) | 117-81-7 (ED/67/2008) | Sleeve (PVC) |
| | LNX | | | |
| | LNK | | | |
| | LNC | | | |
| | LQR | | | |
| | LNW | | | |
| | LNY | | | |
| | LNT | | | |
| | LNU | | | |
| Type 2 ** | JJD | Bis(2-ethylhexyl) phthalate [DEHP] (※1) | 117-81-7 (ED/67/2008) | Sleeve (PVC) |
| | JJL | | | |
| Type 3 *** | QYX | 4,4'-Diaminodiphenylmethane / 4,4'-Methylenedianiline [MDA] | 101-77-9 (ED/67/2008) | Coating resin |
| | EEC | Dibutyl phthalate [DBP] | 84-74-2 (ED/67/2008) | Coating resin |
| | EEN | | | |

Type 1 *: Aluminum electrolytic capacitors (Screw terminal type)

Type 2 **: Electric double layer capacitors (Screw terminal type)

Type 3 ***: Plastic film capacitors

(※1) Production after October 2016 do not contain any of SVHC 174 (0.1%wt or more)

Printed Name: Nobunari Amano

Title: Deputy General Manager

Division: Nichicon Corporation Quality Assurance Division

Date: August 30, 2017



Signature

| Series | Item No. | Series | Item No. | Series | Item No. |
|--------|----------------|--------|----------------|--------|----------------|
| LNC | LNC2V102MSEF | LNR | LNR1J154MSE | LNU | LNU2G472MTEH |
| LNC | LNC2V122MSEF | LNR | LNR2A683MSE | LNX | LNX2W372MSEAZH |
| LNC | LNC2G102MSEF | LNR | LNR2C223MSE | LNT | LNT2V472MTEANU |
| LNC | LNC2G122MSEF | LNC | LNC2W682MSEH | LNW | LNW2W472MTEDZH |
| LNC | LNC2V152MSEF | LNC | LNC2G822MSEH | LNU | LNUT5682MTEEZH |
| LNX | LNX2G102MSEFBN | LNX | LNX2W472MSEH | LNW | LNW2W392MTEBZH |
| LNC | LNC2W102MSEF | LNX | LNX2G562MSEH | LNW | LNW2H392MTEBZS |
| LNC | LNC2V182MSEF | LNX | LNX2H392MSEH | LNU | LNU2F562MTEAZH |
| LNR | LNR2D332MSE | LNC | LNC2V123MSEH | LNX | LNX2H392MTEANU |
| LNC | LNC2W122MSEF | LNK | LNK2W682MSEHBN | LNU | LNU2G682MTEEZH |
| LNX | LNX2W102MSEFBN | LNK | LNK2V103MSEH | LNX | LNXW6472MTEANU |
| LNC | LNC2G152MSEF | LNK | LNK2V103MSEHBN | LNX | LNXW6682MTEANU |
| LNX | LNX2V152MSEF | LNK | LNK2G822MSEH | LNW | LNW2W472MTECZH |
| LNR | LNR1J333MSE | LNC | LNC2G103MSEH | LNW | LNW2W392MTEAZH |
| LNR | LNR2A153MSE | LNX | LNX2G682MSEH | LNX | LNX2W502QTEANU |
| LNC | LNC2H102MSEF | LNX | LNX2V103MSEH | LNW | LNW2W203MSEANU |
| LNC | LNC2V222MSEF | LNC | LNC2W822MSEH | LNX | LNX2G293MSEAzs |
| LNC | LNC2G182MSEF | LNX | LNX2G822MSEH | LNY | LNY2W182MSEG |
| LNC | LNC2W152MSEF | LNC | LNC2V822MSEJ | LQR | LQR2W472MSEJ |
| LNC | LNC2V272MSEF | LNC | LNC2G682MSEJ | JJL | JJL0E178MSEFBN |
| LNX | LNX2G152MSEF | LNC | LNC2W562MSEJ | QYX | QYX1H102KTP |
| LNR | LNR2A223MSE | LNC | LNC2V103MSEJ | QYX | QYX1H683KTP |
| LNC | LNC2G222MSEF | LNC | LNC2H472MSEJ | LQR | LQR2W122MSEF |
| LNR | LNR2D472MSE | LNC | LNC2G822MSEJ | LNR | LNR1E104MSE |
| LNR | LNR1H683MSE | LNC | LNC2W682MSEJ | LQR | LQR2G272MSEG |
| LNC | LNC2W182MSEF | LNC | LNC2H562MSEJ | LNY | LNY2G332MSEG |
| LNC | LNC2V332MSEF | LNC | LNC2G103MSEJ | LQR | LQR2G332MSEG |
| LNR | LNR1C224MSE | LNC | LNC2V123MSEJ | LNY | LNY2G682MSEG |
| LNR | LNR1K333MSE | LNK | LNK2G103MSEJ | LNY | LNY2G392MSEH |
| LNR | LNR1J473MSE | LNX | LNX2J222MSEJ | LNY | LNY2W392MSEH |
| LNR | LNR1V104MSE | LNX | LNX2H472MSEJ | LQR | LQR2W332MSEH |
| LNX | LNX2L102MSEF | LNC | LNC2W822MSEJ | LQR | LQR2G472MSEH |
| LNX | LNX2G222MSEF | LNR | LNR2E153MSE | LNR | LNR1E334MSE |
| LNR | LNR2D682MSE | LNR | LNR2D223MSEB | LNT | LNT1J683MSE |

| | | | | | |
|-----|----------------|-----|----------------|-----|----------------|
| LNC | LNC2H122MSEG | LNR | LNR2D223MSE | LNT | LNT2W472MSEH |
| LNC | LNC2W182MSEG | LNR | LNR1H224MSE | LQR | LQR2W392MSEJ |
| LNC | LNC2V272MSEG | LNR | LNR2C333MSE | LNY | LNY2G153MSEJ |
| LNC | LNC2G222MSEG | LNC | LNC2V153MSEJ | LNU | LNU2G153MSEJ |
| LNC | LNC2V332MSEG | LNC | LNC2H682MSEJ | QYX | QYX1H223KTP |
| LNC | LNC2H152MSEG | LNC | LNC2G123MSEJ | QYX | QYX2A102KTP |
| LNC | LNC2G272MSEG | LNK | LNK2V123MSEJ | QYX | QYX1H102JTP1FD |
| LNC | LNC2W222MSEG | LNX | LNX2J272MSEJ | EEC | EEC2G156HQA416 |
| LNC | LNC2V392MSEG | LNC | LNC2W103MSEJ | JJD | JJD0E108MSEDBN |
| LNX | LNX2G222MSEG | LNC | LNC2V183MSEJ | JJD | JJD0E138MSEDBN |
| LNC | LNC2H182MSEG | LNC | LNC2H822MSEJ | JJD | JJD0E258MSEFBN |
| LNC | LNC2G332MSEG | LNR | LNR2A104MSE | JJL | JJL0E707MSEDBN |
| LNC | LNC2W272MSEG | LNR | LNR1J224MSE | LNX | LNXX6152QSEANU |
| LNX | LNX2H152MSEG | LNX | LNX2J332MSEJ | LNC | LNC2W332MSEG |
| LNK | LNK2W272MSEG | LNR | LNR1H334MSE | LNR | LNR2C153MSEB |
| LNC | LNC2V472MSEG | LNC | LNC2W123MSEJ | LNX | LNX2G682MTEKTM |
| LNC | LNC2H222MSEG | LNC | LNC2G153MSEJ | LNU | LNU2W682MSEH |
| LNC | LNC2G392MSEG | LNK | LNK2G153MSEJ | LNR | LNR2E473MSE |
| LNR | LNR1J683MSE | LNX | LNX2H822MSEJ | QYX | QYX1H154KTP |
| LNX | LNX2L122MSEG | LNK | LNK2H822MSEJ | LQR | LQR2W681MSEC |
| LNK | LNK2G392MSEG | LNX | LNX2L562MSEJ | LNY | LNY2G183MSEJ |
| LNC | LNC2W332MSEGBN | LNX | LNX2L562MSEJBB | LNY | LNY2W562MSEH |
| LNC | LNC2V562MSEG | LNX | LNX2J392MSEJBB | LNY | LNY2G182MSEG |
| LNC | LNC2G472MSEG | LNX | LNX2V153MSEJ | QYX | QYX2A104KTP |
| LNR | LNR2D103MSE | LNX | LNX2J392MSEJ | QYX | QYX2A103KTP |
| LNX | LNX2J102MSEG | LNX | LNX2W103MSEJ | QYX | QYX1H473KTP |
| LNX | LNX2V472MSEG | LNC | LNC2H103MSEJ | QYX | QYX1H104KTP |
| LNC | LNC2W392MSEG | LNC | LNC2V223MSEJ | QYX | QYX1H153KTP |
| LNC | LNC2G562MSEG | LNC | LNC2G183MSEJ | QYX | QYX1H334KTP |
| LNC | LNC2V682MSEG | LNC | LNC2W153MSEJ | QYX | QYX2A333KTP |
| LNR | LNR2A473MSE | LNR | LNR1J334MSE | QYX | QYX2A473KTP |
| LNR | LNR1J104MSE | LNX | LNX2W123MSEJ | LQR | LQR2G222MSEF |
| LNC | LNC2W472MSEG | LNR | LNR2A154MSE | LQR | LQR2G681MSEC |
| LNK | LNK2G562MSEG | LNX | LNX2L682MSEJ | LNY | LNY2G102MSEF |
| LNC | LNC2W562MSEG | LNR | LNR2D152MSEN | LNT | LNT2D332MSE |

| | | | | | |
|-----|----------------|-----|----------------|-----|----------------|
| LNC | LNC2G682MSEG | LNR | LNR1H153MSE | LNY | LNY2W222MSEG |
| LNC | LNC2W222MSEH | LNR | LNR1J103MSE | LNY | LNY2W272MSEG |
| LNC | LNC2G272MSEH | LNR | LNR1C473MSE | LQR | LQR2W222MSEG |
| LNC | LNC2V392MSEH | LNR | LNR1C683MSE | LNX | LNXX6222QSECNU |
| LNC | LNC2G332MSEH | LNR | LNR1H223MSE | LQR | LQR2W272MSEH |
| LNC | LNC2W272MSEH | LNC | LNC2W332MTEG | LNY | LNY2G472MSEH |
| LNC | LNC2W272MSEHBN | LNU | LNU2W392MTEH | LNX | LNWX6562MTEANU |
| LNC | LNC2G392MSEH | LNT | LNT2W332MTEH | LNX | LNXX6342KTEBTM |
| LNC | LNC2V472MSEH | LNX | LNX2H103MSEK | LQR | LQR2W682MSEH |
| LNC | LNC2W332MSEH | LNX | LNX2G153MSEK | LQR | LQR2W822MSEJ |
| LNC | LNC2H272MSEH | LNX | LNX2L822MSEK | LQR | LQR2W103MSEJ |
| LNC | LNC2W392MSEH | LNX | LNX2W153MSEK | LNY | LNY2W123MSEJ |
| LNC | LNC2V562MSEH | LNX | LNX2H123MSEK | LNR | LNR2C683MSEN |
| LNC | LNC2G472MSEH | LNR | LNR1J474MSE | LNY | LNY2W153MSEJ |
| LNR | LNR2C153MSE | LNX | LNX2J562MSEK | QYX | QYX1H222KTP |
| LNC | LNC2G562MSEH | LNX | LNX2V273MSEK | QYX | QYX1H222JTP1FD |
| LNX | LNX2G332MSEH | LNX | LNX2W183MSEK | QYX | QYX1H103KTP |
| LNK | LNK2W332MSEH | LNR | LNR1V105MSE | LNY | LNY2W332MSEH |
| LNC | LNC2V682MSEH | LNX | LNX2G223MSEK | LQR | LQR2G392MSEH |
| LNC | LNC2H332MSEH | LNR | LNR2A224MSE | LNX | LNX2G472MSMHTM |
| LNX | LNX2L182MSEH | LNX | LNX2L103MSEK | LNY | LNY2G562MSEH |
| LNC | LNC2V822MSEH | LNR | LNR2C104MSE | LNY | LNY2W472MSEH |
| LNC | LNC2W472MSEH | LNX | LNX2L103MSEKBN | LNY | LNY2G822MSEJ |
| LNR | LNR2E103MSE | LNR | LNR1H684MSE | LNY | LNY2W682MSEJ |
| LNC | LNC2G682MSEH | QYX | QYX2A104KTP3TA | LNY | LNY2W822MSEJ |
| LNC | LNC2H392MSEH | EEC | EEC2G156HZA416 | LNY | LNY2G103MSEJ |
| LNX | LNX2G472MSEH | LNR | LNR1V114MTEANU | QYX | QYX1H472KTP |
| LNC | LNC2V103MSEH | LNT | LNTW6322MSEATM | QYX | QYX2A102JTP |
| LNC | LNC2W562MSEH | LNR | LNR1J723MTEANU | QYX | QYX1H332KTP |
| LNR | LNR1K104MSE | LNX | LNXX6222QSEBNU | | |